

Oil Field Environmental Incident Summary

Incident: 20150619220458 **Date/Time of Notice:** 06/19/2015 22:04

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: WALLACE 21X-2B

Field Name: WEST CAPA

Well File #: 22325

Date Incident: 6/19/2015 **Time Incident:** 06:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 97

Sec: 2

Qtr:

Location Description:

Submitted By: Jeremy Waldschmidt

Received By:

Contact Person: Jeremy Sorenson
10481 1A ST SW
Killdeer, ND 58640

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Blowout

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	10	Barrels		

Brine

Other

Description of Other Released Contaminant:

N/A

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None.

Areal Extent:

N/A

Potential Environmental Impacts:

None - spill was contained to well pad.

Action Taken or Planned:

Well pad was shut-in post incident. Spill was contained to well pad and impacted material will be hauled to an approved disposal site. Liquids were placed back into production tanks.

Wastes Disposal Location: R360 Disposal and production tank.

Agencies Involved:**Updates**

Date: 6/22/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to blowout, remained on location within the diking, according to the report. NDIC retains oversight.